

## **Datakey - Product Change Notification**

 PCN Number:
 20240412

 Notice Date:
 12 April 2024

Notification Subject: Product Change Notification (PCN)

## **Summary Description:**

This product change notification (PCN) documents changes being made to the specification drawing for the electrically conductive gasket that is used with panel-mount SlimLine receptacles that have conductive outer shells for better EMI/EMC performance, including popular models like the SR4310EI and SR4310EL SlimLine receptacles. See below for a complete list of receptacles impacted by this PCN. The specification for the gasket material is NOT changing. The only thing that is changing are the dimensional tolerances, primarily dimensions with  $\pm$  0.015" tolerance are changing to  $\pm$ 0.020".

Affected Products: Gasket EMI	Part Numbers: 327-0376-001A
SR4310El Receptacle, IP67, EMI, Header	606-0067-002A
SR4310Cl Receptacle, IP67, EMC, Header	606-0067-003A
SR4310EL Receptacle, IP67, EMI, Locking	606-0067-012A
SR4310CL Receptacle, IP67, EMC, Locking	606-0067-013A
SR4310CF Receptacle, IP67, EMC, FPC	606-0067-023A
SR4410El Receptacle, IP67, EMI, Header	606-0071-002A
SR4410Cl Receptacle, IP67, EMC, Header	606-0071-003A
SR4410EL Receptacle, IP67, EMI, Locking	606-0071-012A
SR4410CL Receptacle, IP67, EMC, Locking	606-0071-013A
SR4410CF Receptacle, IP67, EMC, FPC	606-0071-023A
UR4310El Receptacle, IP67, EMI, Header	606-0074-002A
UR4410El Receptacle, IP67, EMI, Header	606-0078-002A
Special SR4310El Receptacle, IP67, EMI, No Header	699-0114-000A
Special SR4410El Receptacle, IP67, EMI with SPI Line Driver	699-0159-002A

## **Notice Details:**

The drawing for the electrically conductive gaskets (part number 327-0376-001A) that are used on the SlimLine receptacle models listed above has been modified. Dimensions that previously had a tolerance of  $\pm 0.015$  inches now have a tolerance of  $\pm 0.020$  inches with one exception. The overall length of the gasket remains at 1.54 inches  $\pm 0.015$  inches. Also, the thickness of the gasket remains unchanged at 0.032 inches  $\pm 0.005$  inches. The gasket material has not changed. Because there is no change in form, fit or function, the part numbers and revision letters of the receptacles listed above will not be changing. Gaskets made per the updated drawing will be used in production starting in late April 2024.

If you have any guestions regarding this PCN, please contact the Datakey Customer Care Team.

## **Contact Information:**

**Customer Care Team** 

- +1 (800) 523-6996
- +1 (218) 829-9797

CCT@datakey.com

